RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11627

RECEIVED FROM E.A.I. #9

DATE REC'D. 3-21-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.
	322		01	5	21			

C R ACCT. OR W.O. NO.

S.O. NO.

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
95	738225-1 Flange Film Spool	95 ✓		
96	738225-2 Flange Film Spool	96 ✓		
	IRB #04763			
	To supersede Rec. #11615			

RECEIVED BY J. Barcelos

INSPECTED BY DRA

DATE 3/21/57

REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1069

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11637

RECEIVED FROM E.A.I. #9

DATE REC'D. 3-21-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.
	322		6	D	[illegible]			

O R ACCT. OR W.O. NO.

S.O. NO.

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
10	738296 Lid Assbly Switch	10		
	IRB #04791			

RECEIVED BY J. Barcelos

INSPECTED BY

DATE 3-21-57

REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1069